

Dual pressure and temperature output from each sensor.

View & record record up to 500 times per second

25 bar, 160 bar, 400 bar & 700 bar sensors available

Connect, view & record up to 8 sensors at one time using standard USB hubs.

Watchlog USB software automatically detects any connected sensors.

Min / max values and settable alarm limits.

Manual, timed or scheduled recording options.

Graph zooming and annotation even during recording.

PDF and CSV tes export options.

SECTORS
Industrial, Food & Beverage
Pulp & paper, Mobile
hydraulics, Pump &
component testing

INCLUDED WITH EACH SENSOR IS OUR WINDOWS PC/
TABLET SOFTWARE FOR SIMPLE, QUICK AND COSTEFFECTIVE PRESSURE & TEMPERATURE MEASUREMENT OF
UP TO 8 WATCH IO SIER SENSORS AT THE SAME TIME.

Users can view the measurements in numerical, graph or both simultaneously. Test data can be viewed, zoomed and annotated during or after recording and data can then be exported for easy test file management.











